

Presented to:

2009 U.S. Army Corrosion Summit



RDECOM



Engineering Support / Corrosion Prevention & Control Evaluation

Approved for public release; distribution unlimited. Review completed by the AMRDEC Public Affairs Office. 12 Jan 2009; FN3805.



TECHNOLOGY DRIVEN. WARFIGHTER FOCUSED.

February 5, 2009



Presented by:


Don R. Duran

**Aviation and Missile Research,
Development and Engineering Center**

Report Documentation Page				Form Approved OMB No. 0704-0188	
Public reporting burden for the collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to a penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.					
1. REPORT DATE 05 FEB 2009		2. REPORT TYPE		3. DATES COVERED 00-00-2009 to 00-00-2009	
4. TITLE AND SUBTITLE Engineering Support / Corrosion Prevention & Control Evaluation				5a. CONTRACT NUMBER	
				5b. GRANT NUMBER	
				5c. PROGRAM ELEMENT NUMBER	
6. AUTHOR(S)				5d. PROJECT NUMBER	
				5e. TASK NUMBER	
				5f. WORK UNIT NUMBER	
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) U.S. Army Research, Development and Engineering Command, Aviation and Missile Research, Development and Engineering Center ,600 Chennault Circle,Redstone Arsenal,AL,35898				8. PERFORMING ORGANIZATION REPORT NUMBER	
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)				10. SPONSOR/MONITOR'S ACRONYM(S)	
				11. SPONSOR/MONITOR'S REPORT NUMBER(S)	
12. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution unlimited					
13. SUPPLEMENTARY NOTES 2009 U.S. Army Corrosion Summit, 3-5 Feb, Clearwater Beach, FL					
14. ABSTRACT					
15. SUBJECT TERMS					
16. SECURITY CLASSIFICATION OF:			17. LIMITATION OF ABSTRACT Same as Report (SAR)	18. NUMBER OF PAGES 18	19a. NAME OF RESPONSIBLE PERSON
a. REPORT unclassified	b. ABSTRACT unclassified	c. THIS PAGE unclassified			



- Aircraft Corrosion
 - Corrosion Prevention & Control Evaluation
 - 3D Mapping
 - Pressure Washing
- Engineering Support
 - Maintenance Engineering Calls
 - Maintenance Engineering Order
 - Corrosion Prevention Techniques
 - ACE/Corrosion website





AH-64 A/D



CH-47 D/F



UH-60 A/L/M



OH-58 D



- CPCE is performed concurrently with the Airframe Condition Evaluation (ACE)
- The evaluation collects environmental, operational, and maintenance data
- These variables enable Maintenance Engineering Division (MED) to develop corrosion prevention measures for Army-wide implementation






- Trained ACE evaluators examine aircraft using Technical Bulletins developed for each platform
- Evaluators document defects of indicators for each aircraft with location positioning F.S., W.L., B.L.
- Discrepancy Data gathered in field, compiled in ACE Database, and evaluated by the MED






- Quick visual reference of defects identified during evaluations
- Provides historical data for long-term trend analysis
- User defined queries allow for detailed analysis






● Corrosion 2004-2008






● Corrosion 2004-2008






● Corrosion 2004-2008





● Corrosion 2004-2008





Extreme surface corrosion in fuel cell area



AGUADILLA, PR
US CUSTOMS
UH-60A 7923344
CORROSION IN FUEL CELL AREA
F.S.400-443, W.L. 198-93-237, 39, 31B, L.3, 59-45, 52


79-23327 r/s stringer San Juan, Pr



Corroded Stringer


Corrosion can be prevented by:

1. Education: Corrosion training
2. Performing required maintenance inspections to identify corrosion
3. Performing good maintenance practices: use TMs, protect working surfaces, wash and clean on schedule
4. Using QPL approved cleaners and Corrosion Preventive Compounds (CPC)



Gen-MIM-2005-005 & TM 1-1500-344-23:

1. Use of Foam Cleaning methods
2. Maximum of 175 PSI w/ fixed, flat, wide-angle nozzles (> 30 Degrees), 12 inches from surface
3. Rinse at an angle between 15 and 30 degrees
4. High pressure causes:
 - Removes and damages paints and sealants
 - Forces water into seals
 - Structural damage to joints/honeycomb/thin structures.
 - Water intrusion into electronic components





AH-64 A/D



Engineering Support

CH-47 D/F



UH-60 A/L/M



OH-58 D




- MEC: Are initiated by depot or field maintenance personnel requesting AMRDEC engineering support
- Typical requests are for deviations, special repairs, and to resolve DMWR inadequacies
- Engineering dispositions include clarifications, one time deviations, or short term deviations for depot programs (< 30 days)

OH-58 XMSN Strap



AH-64 Engine Mount







- MEO: These engineering documents are issued to enact permanent changes to AMCOM Depot Maintenance Work Requirements (DMWRs) or Technical Manuals (TMs)



CH-47 Floor Former

MAINTENANCE ENGINEERING ORDER (AMCOM Reg 750-11)						MEO NO. C4697	
TITLE CH-47 Cruise Guide Indicator, P/N 114VS805-3 and 114VS805-4						DATE DEC 05 2003	PAGE 1 of 1
APPLICABILITY INTERIM USE OF THIS MEO IS AUTHORIZED FOR DEPOT MAINTENANCE UNTIL AFFECTED DOCUMENT IS UPDATED.						TOLERANCES Unless otherwise noted, dimensions are in inches and tolerances are: Fractional +/- 1/32 Decimal +/- .010 Angular +/- 1/2 degrees	
DOCUMENT(S) AFFECTED DMWR 55-8810-383, Dtd 15 Apr 1990						CSI Critical Characteristic <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
DOCUMENT CHANGE IS REQUIRED						REFERENCES FOR RDECOM USE ONLY CH-47 DAA Project 28479C 12/5/2003	
PURPOSE OR PROBLEM Correction to IPB text.							
PROJECT ENGINEER  Humberto Hernandez, Jr.			ENGINEERING REVIEW			ENGINEERING RELEASE  Humberto Hernandez, Jr.	
PUBLICATION CHANGE REQUEST: REQUEST THAT THE FOLLOWING DATA BE INCLUDED IN THE NEXT CHANGE OR REVISION TO THE PUBLICATION IDENTIFIED ABOVE.							
ITEM NO.	PAGE NO.	PARA-GRAPH	LINE NO.	FIGURE NO.	TABLE NO.	CHANGES (EXACT WORDING OF CHANGE MUST BE GIVEN)	
	4-7.			4-1.		CHANGE the Part Number for Item # 25, Movement Assembly, from "370B2" to "37082"	
MED FORM 16-OCT-03 1401-R-E							
Click to insert figure sheet			Click to insert formatted continuation sheet			Click to insert unformatted continuation sheet	




•Past and Present Initiatives

- RockHard Coating
- Av-Dec seals
- Cor-Ban CPCs
- Dual-Tape Connector Wrap

•Future Initiatives

- Army-wide use of Tagnite for Mg components
- Envelop Protective Covers
- Laser cladding
- Pre-manufacturing technologies
 - Advanced metals
 - Advanced composites
 - Advanced adhesives
 - Ect....



Conclusion

- CPCE enables early detection of emerging structural and corrosion issues
- ACE/CPCE data collection defines the impact of corrosion and aircraft stresses
- Analysis of ACE/CPCE data provides solutions that will continue to reduce the cost of maintenance and promote readiness



TECHNOLOGY DRIVEN. WARFIGHTER FOCUSED.



Welcome to the Aviation Engineering Directorate (AED)- Maintenance Engineering Division (MED) ACE/Corrosion Website

The site provides you ACE & Corrosion Prevention resources and a place
for your comments & questions. Contact us @

DSN 861-4041

(361) 961-4041

or E-mail at: corrosion@amrdec.army.mil

Questions?